


ПЕС-2520РБ



NO.	DESCRIPTION	NO.	DESCRIPTION
1	arresting lever	51	washer $\phi 6$
2	screw M8	52	bearing 6201
3	gasket 8	53	65z gear
4	spring cover	54	bearing 6001
5	pin $\phi 4 \times 18$	55	bearing cover
6	spring	56	bearing washer
7	gasket $\phi 13 \times \phi 18 \times 2.5$	57	bearing 6203
8	gasket $\phi 12.5 \times \phi 18 \times 1.5$	58	rotor
9	iron head	59	fan shroud
10	bumper	60	screw M5 $\times$ 60
11	o ring $\phi 23.5 \times \phi 5.2$	61	washer $\phi 5$
12	drill shank sleeve	62	stator
13	rubber cover	63	tension spring
14	broken ring	64	safety gasket
15	gasket $\phi 57.5 \times \phi 68.5 \times 2$	65	gear box
16	bumper1	66	oil bowl gasket
17	rubber handle	67	oil bowl
18	locknut m8	68	screw M4 $\times$ 12
19	front handle clamp	69	oil core
20	front handle holder	70	brush cover
21	handle level	71	brush gasket
22	split pin	72	brush cover
23	front pocket	73	brush carbon
24	screw M8 $\times$ 40	74	brush holder
25	gasket $\phi 8$	75	screw M5 $\times$ 8
26	ring $\phi 62 \times \phi 2$	76	back cover
27	screw M8 $\times$ 16	77	screw M5 $\times$ 14
28	cylinder	78	rubber washer
29	piston ring	79	oil cover
30	piston pin	80	gasket $\phi 20.5 \times \phi 2$
31	piston	81	oil hole
32	connecting rod	82	handle cover
33	eccentric shaft gasket	83	screw M4 $\times$ 14
34	needle NK1820	84	screw M4 $\times$ 10
35	pin $\phi 5 \times 12$	85	switch
36	eccentric shaft	86	switch rubber
37	KEY	87	main handle
38	screw M5 $\times$ 14	88	screw M6 $\times$ 25
39	bearing cover	89	press board
40	bearing 6205	90	cable cover
41	gasket	91	cable
42	middle cover		
43	range ring		
44	big gear		
45	snap spring $\phi 22$		
46	bearing 6302		
47	up cover		
48	mark		
49	screw M6 $\times$ 45		
50	spring washer $\phi 6$		